

Quality aircraft since 1974

SERVICE LETTER - July 2014

Issue Date Tuesday, July 22, 2014, Rev 1

Subject/Purpose Corrosion inspection

Affected Models All

<u>Compliance Time</u> Within the next 50 hours

<u>Maintenance</u> As per AC 43.13 and CH2000 Service Manual. Also see "SERVICE BULLETIN February 2011"

Required Parts None

Inspection Frequency

Annual


Subject/Purpose

Zenair Ltd was made aware of a canopy door hinge getting damaged due to corrosion and possible excessive wear.

Preventative Measures


Inspect the door hinges at the canopy for corrosion and or deformation. If the doors are not closed fully when engine is ON, wind loads could damage the door hinges.

- Beside the red door handles:



Above label must be installed on the inside of the doors. Service Letter of October 08-02 already addresses this label.

As many CH2000 aircraft are now more than 10 years old, it is important to properly inspect the aircraft for corrosion. **All moving parts must be lubricated and free of corrosion**. Following page is from the Service Manual and is a general purpose chart that does not cover all items to be lubricated. Cabin controls such as the rudder pedals and yoke system are not shown on the chart but MUST be inspected and lubricated.



Page two of two