



Quality aircraft since 1974

SERVICE LETTER October 15 03

Issue Date:

10/15/2003

Subject/Purpose:

Flap Switch Tab

Affected Models:

All CH2000 models manufactured before August 2003

Compliance Time:

Next inspection

Inspection:

Check the Flap Switch to see if a large white tab is attached to it.

Required Items:

Part Number	Description	Quantity
20-C-15-14/0	Flap Switch Tab	1

Installation:

Heat Flap Switch nylon tab with heat gun and push onto existing flap switch toggle. Once cool, it must be tight.

Contact Zenair Ltd. for more information.

***ZENAIR LTD, HURONIA AIRPORT, MIDLAND, ONTARIO, CANADA L4R 4K8
TEL:(705) 526-2871 - FAX:(705)526-8022***