

ZENAIR LTD, HURONIA AIRPORT, MIDLAND, ONTARIO, CANADA L4R 4K8 TEL:(705) 526-2871 - FAX:(705)526-8022

SAFETY ALERT – AUGUST, 2023

Issue Date

AUGUST, 2023, Rev. 0

Subject/Purpose

Placard Update / Replacement

Affected Models

CH 650 & CH 750 SLSA

Compliance Time

Before next flight

Inspection Frequency

One-time

Background

The one placard needed to be updated before the next flight.

MIXTURE placard on the instrument panel at the mixture control.

From: MIXTURE PULL RICH

To: MIXTURE PUSH RICH

Replace the one page in the POH 9.2 and replace the placard to MIXTURE PUSH RICH on the instrument panel.

Update the Revisions – Update Log on page 0-3

LIMITATION PLACARDS

No Intentional Spins Warning:

The following placards are installed: Instrument panel area:

THIS AIRCRAFT WAS MANUFACTURED IN ACCORDANCE WITH LIGHT SPORT AIRCRAFT AIRWORTHINESS STANDARDS AND DOES NOT CONFORM TO STANDARD CATEGORY AIRWORTHINESS REQUIREMENTS

Above placard must be posted in the aircraft passenger area so that it is visible to both the pilot and passenger upon entry or when seated in the aircraft

NO INTENTIONAL SPINS

Other placards on instrument panel: NO SMOKING Registration # Hircraft THROTTLE PULL CLOSE MIXTURE PUSH RICH CARB, HEAT PULL OPEN Tanufacturing & Devign, LLC Other placards in cabin area: TRIM FLAPS NOSE UP UP TRIM NOSE DOWN FLAPS

DOWN

Placard near Door Latch:

Do Not Unlatch Door In Flight

1

MARCH 2009 9-2