



Quality aircraft since 1974

SERVICE LETTER February 01 03

Issue Date:

February 01 2003

Subject/Purpose:

Gross weight increase as per CH2000 FAA approved Type Certificate Data Sheet No. TA5CH Rev. 8

Affected Models:

Affected models: All US registered aircraft CH2000, which are not spin certified.

Compliance Time:

Anytime

Inspection:

Non

Required Items:

Nov. 2002 Rev. 14	Flight Manual	Qty 1
Dec 02 2002	FAA Flight Supplement #1 for US registered aircraft only	Qty 1
Nov. 2002	Service Manual	Qty 1

The Airspeed Indicator operating markings must be changed due to a higher stall speed as indicated in the FAA Flight Supplement #1 page 2.1 - FAA 4 Dec. 02. This can be done by taping on the new operating range decals on the face of the instrument, or by purchasing a new Airspeed Indicator from AMD, part number 20-M-96-1/0.

Operating range decals can be purchased from Aircraft Spruce & Specialty Co., 1-877-477-7823, and part number 10-03905 for about \$2.95/set.

Complete weight & Balance form in the FAA Flight Supplement #1 page 6.3 - FAA 4 Dec. 02 and put in aircraft with other required documentation. Update Airframe Log Book.

For additional information please contact Zenair Ltd.

ZENAIR LTD, HURONIA AIRPORT, MIDLAND, ONTARIO, CANADA L4R 4K8

TEL:(705) 526-2871 - FAX:(705)526-8022 Page one of one